



philips-ag9015



- Home
- Realizzazioni a valvole
- Restauri radio
- Riparazioni
- Akai CD25
- AT 80W ultralineare
- Audio Note m1 phono
- Audio Note P1SE
- Fisher fm2421
- Grundig V30
- Leak trough line 3
- Luxman DZ112
- Luxman LV105
- Mitsubishi It 5v
- Mivar r481
- Perreaux PMF 3150
- Perreaux SM3
- Philips 22RH541/15R
- Philips 26CS3490-41R
- Philips AG9015
- Philips cd960-1
- Philips cd960-2
- Radio Hachette
- Registratore Pioneer RT707
- Telefunken TA350 B
- Telefunken music center
- Voxson H302
- Yamaha A1000
- Watt Radio hifi 1015
- Modifiche
- Diffusori
- Varie
- Riparazioni TV
- Contatto

Apparato e modello:	Philips AG9015
difetti:	1) condensatori elettrolitici in dispersione 2) una EF86 generava fruscio di fondo 3) una EL86 finale audio guasta (tutti difetti attribuiti all'età)
:	











